DART SERVICE INSTRUCTION

TO AMEND MANUFACTURING PROCESS PROCEDURE MPP-169 REV. E AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA505-1 REV. 4 OR LATER APPROVED REVISIONS

REF. TCCA STC: SH18-9 REF. FAA STC: SR04133NY REF. EASA STC: 10067422 REF. CAAC STC: VSTC0993 REF. MEXICO STC: 1A-623/2019 REF. JCAB STC: STC-440-OSA

1.0 PURPOSE

The purpose of this DART Service Instruction (DSI) is to provide DART Aerospace Repair and Overhaul facilities with instructions to replace a 645.5902-270-000-17 Valve Assembly with a 655.3902-270-000-17 Valve Assembly, when performing an overhaul of a 651.6501 Reservoir Assembly.

2.0 OVERHAUL PROCEDURE

One of the following two options may be chosen during the next overhaul of a 651.6501 Reservoir Assembly.

2.1 OPTION 1: REPLACE VALVE ASSEMBLY

- (a) Remove the currently installed 645.5902-270-000-17 Valve Assembly and replace it with a new 655.3902-270-000-17 Valve Assembly.
- (b) Continue overhaul of the 651.6501 Reservoir Assembly per 651.6500 Rev. D or later approved revisions.

2.2 OPTION 2: REWORK VALVE ASSEMBLY

- (a) Disassemble the currently installed 645.5902-270-000-017 Valve Assembly per MPP-169. During the disassembly, retain the components listed in Table 1 and discard the remaining components.
- (b) Clean the retained components per MPP-241.
- (c) Refer to Section 3.0 of this DSI for the components required to rework the 645.5902-270-000-17 Valve Assembly to a 655.3902-270-000-17 Valve Assembly.
- (d) Identify the 655.3810 Valve Body with a new P/N and S/N per MPP-241. Additional identification may be required per MPP-120.
- (e) Assemble the 655.3902-270-000-17 Valve Assembly per MPP-241.
- (f) Continue overhaul of the 651.6501 Reservoir Assembly per 651.6500 Rev. D or later approved revisions.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

BY: D. SHEPHERD (DE #02)

DATE: CERT. NO.: ISSUE NO.:

23.05.05 SH18-9 1

Α	NEW ISSUE (REASON ECR 529)			23.05.05	
REV.			DESCRIPTION BY	DATE	
DESIGN		KPT	DART AEROSPACE		
DRAWN		KPT	HAWKESBURY, ONTARIO, CANADA		
CHECKED		SAD	DRAWING NO.	REV. A	
MFG. APPR.		N/A	DSI 9904	SHEET 1 OF 2	
APPROVED		IT "	TITLE	SCALE	
DE APPR.		DS-	RESERVOIR ASSEMBLY OVERHAU	L NTS	
DATE 23.05.05			COPYRIGHT © 2023 BY DART AEROSPACE THIS DOCUMENT IS PRINATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OF COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT		

Table 1: Components to Retain

YTÇ	P/N	DESCRIPTION
1	601.2413	SAFETY DISC RETAINER
1	645.6510	PUNCTURE DISC RETAINER
1	645.6810	PULL ROD HOUSING
1	645.6910	PULL ROD
1	645.7710	SHROUD
1	647.2910	SPRING CAP

3.0 PARTS LIST

The following components are required if reworking a 645.5902-270-000-17 Valve Assembly to a 655.3902-270-000-17 Valve Assembly per Section 2.2 of this DSI.

QTY -011	P/N	DESCRIPTION
Χ	DSI 9904-011	VALVE REWORK KIT
1	655.3999	655.3900 VALVE ASSEMBLY OVERHAUL KIT
1	601.3739	GAUGE
1	645.6210	BAYONET HOUSING
1	650.6211	BANJO -6
1	654.6410	FILL PORT
1	654.6411	PLUG FITTING
1	654.6412	FILL PISTON FITTING
1	655.2710	SAFETY DISC ADAPTER
1	655.2711	FILL PORT ADAPTER
1	655.2712	GAUGE ADAPTER
1	655.2713	THERMAL ADAPTER
1	655.3601	SWIVEL FITTING ASSEMBLY
1	655.3810	VALVE BODY

DESIGN	KPT	DART AEROSPACE HAWKESBURY, ONTARIO, CANADA	
DRAWN	KPT		
CHECKED	SAD	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9904 _{SI}	HEET 2 OF 2
APPROVED	IT /	TITLE	SCALE
DE APPR.	DS-	RESERVOIR ASSEMBLY OVERHAUL	NTS
DATE 23.0	5.05	COPYRIGHT © 2023 BY DART AEROSPACE THIS DOCUMENT IS PRIVATE AND CONTIDENTAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT	